

AC AXIAL FANS –  
SICKLED BLADES

AC AXIAL FANS –  
BLADES WITH COMPOSITE  
MATERIAL (PP/AP)

AC AXIAL FANS –  
PADDLE BLADES

UL LISTED AXIAL FANS


ACCESSORIES

CONNECTION DIAGRAMS

APPENDIX


# Connection diagrams

## ■ Connection diagrams 0301-1-0002




Rotation	L	N	PE	Join together	Protection device	Winding connection
CCW from cable side	U2 (black)	U1 (blue)	PE (ye/gr)	[CA1, U2] [CA2, Z2]	Internally connected	Permanent split phase capacitor motor


## ■ Connection diagrams 0301-1-0044



## ■ Connection diagrams 0301-1-0043




## ■ Connection diagrams 0301-1-0026



Rotation	L	N	PE	Join together	Protection device	Winding connection
CW from cable side	U2 (black)	U1 (blue)	PE (ye/gr)	[CA1, U2] [CA2, Z2]	Internally connected	Permanent split phase capacitor motor



### Connection diagrams 0301-1-0029




#### Connection options:

Rotation	L1	N	PE	Protection device	Join together	Winding connection
CW from cable side	U1	U2	PE	TK, TK	[CA1, U1] [CA2, Z2] [U2, Z1]	1.ph motor with capacitor and thermal contacts.

\* Temperature monitors (TK) built in to the winding serve as motor cut-out switch and must be connected to the outside control unit!

### Connection diagrams 0301-1-0049




#### Connection options:

L1	L2	L3	PE	Protection device	Join together	Winding connection
U1	V1	W1	PE	TK, TK	[U2,V2,W2]	STAR (Y) - high voltage (STANDARD)
U1	V1	W1	PE	TK, TK	[U1,W2]; [V1,U2]; [W1,V2]	DELTA (Δ) - low voltage

\* Changing of rotation direction by interchanging of 2 phases!

\* Temperature monitors (TK) built in to the winding serve as motor cut-out switch and must be connected to the outside control unit!

### Connection diagrams 0301-1-0048



#### Connection options:


L1	L2	L3	PE	Protection device	Join together	Winding connection
U1	V1	W1	PE	TK, TK	[U1,W2]; [V1,U2]; [W1,V2]	DELTA (Δ) - high speed (STANDARD)
U1	V1	W1	PE	TK, TK	[U2,V2,W2];	STAR (Y) - low speed

\* Changing of rotation direction by interchanging of 2 phases!

\* Without bridges when using speed-change over switch!

\* Temperature monitors (TK) built in to the winding serve as motor cut-out switch and must be connected to the outside control unit!

### Connection diagrams 0301-1-0035




#### Connection options:

Rotation	L1	N	PE	Protection device	Join together	Winding connection
CCW from cable side	U1	U2	PE	TK, TK	[U1, Z1] [U2, CA1] [Z2, CA2]	1.ph motor with capacitor and thermal contacts.

\* Temperature monitors (TK) built in to the winding serve as motor cut-out switch and must be connected to the outside control unit!

### ■ Connection diagrams 0301-1-0033




#### Connection options:

L1	L2	L3	PE	Protection device	Join together	Winding connection
U1	V1	W1	PE	TK, TK	[U1,W2]; [V1,U2]; [W1,V2]	DELTA ( $\Delta$ ) - high speed (STANDARD)
U1	V1	W1	PE	TK, TK	[U2,V2,W2];	STAR ( $Y$ ) - low speed

- \* Changing of rotation direction by interchanging of 2 phases!
- \* Without bridges when using speed-change over switch!
- \* Temperature monitors (TK) built in to the winding serve as motor cut-out switch and must be connected to the outside control unit!

### ■ Connection diagrams 0301-1-0031




#### Connection options:

L1	L2	L3	PE	Protection device	Join together	Winding connection
U1	V1	W1	PE	TK, TK	[U1,W2]; [V1,U2]; [W1,V2]	DELTA ( $\Delta$ ) - high speed (STANDARD)
U1	V1	W1	PE	TK, TK	[U2,V2,W2];	STAR ( $Y$ ) - low speed

- \* Changing of rotation direction by interchanging of 2 phases!
- \* Without bridges when using speed-change over switch!
- \* Thermal contacts rating: AC 250V, 2.5A at  $\cos \varphi=1.0$ , 1.6A at  $\cos \varphi=0.6$ , temperature sensing.

### ■ Connection diagrams 0301-1-0034



#### Connection options:

L1	L2	L3	PE	Protection device	Join together	Winding connection
U1	V1	W1	PE	TK, TK	[U2,V2,W2]	STAR ( $Y$ ) - high voltage (STANDARD)
U1	V1	W1	PE	TK, TK	[U1,W2]; [V1,U2]; [W1,V2]	DELTA ( $\Delta$ ) - low voltage

- \* Changing of rotation direction by interchanging of 2 phases!
- \* Temperature monitors (TK) built in to the winding serve as motor cut-out switch and must be connected to the outside control unit!